


## Strain Pole Attachments

Note: Strap all signal cables to the side of the pole with 3/4" stainless steel straps when the distance between the spanwire attachment clamp and the weatherheads exceeds 36"



|TS&SU#||TS Signals\*#orKgroups\*Structures\*Drawings\*2012 Standard Strain Mole Uwgs |-tina